

**SEWING MACHINE TABLE
COMFORT 1Q (C 1Q+)**



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION




STORAGE




INDICATING MARK




SPECIAL OPERATION



WATCH








EQUALITY














EVEN SURFACE










010001	1x	010002	1x	010004	1x	010006	1x
010007	1x	010008	1x	010009	1x	010011	5x
010012	5x	010013	5x	010014	1x	010015	1x
010017	1x	010026	1x	010028	2x	010030	1x
010034	1x						



 020003 2x	 020004 2x 020005 2x	 020006 2x	 020008 2x	 1x 020011
---	---	---	--	---


 1x 020012	 7x 020013 CR	 7x 020013 CL
	 7x 020015 DR	 7x 020015 DL

 020018 4x	 020020 4x	 020034 4x
---	---	--

 030001 3 * 16 32x	 030002 3,5 * 16 56x	 030003 6,2 * 50 22x	 030005 4,2 * 16 10x	 030006 2,9 * 13 6x	 030007 φ 6 2x	 030008 φ 4 4x	 030009 M4 * 20 4x	 030010 φ 6 4x	 030031 φ 10 s2,5 4x
---	---	---	---	--	---	---	---	---	---




 030011 φ 15 22x	 030012 φ 18 8x	 030013 L 35 8x	 030014 φ 15 h 12 8x	 030015 φ 8 * 30 18x	 030016 φ 8 * 30 10x	 030017 φ 15 h 10 10x	 030022 M 10 4x	 030023 φ 10 4x
---	--	--	---	---	--	--	--	--


 030033 4,2 * 13 18x	 030028 3,9 * 16 8x
---	--





COMFORT 1Q+










<p>010018 1x</p>	<p>020001</p> <p>2x</p> 	<p>7x 020019</p> 	<p>030004</p>  <p>$\phi 5 * 30$</p> <p>2x</p>	<p>030033</p>  <p>4,2 * 13</p> <p>28x</p>
-------------------------	---	--	---	---






- 6** 7x  030011
 7x  030003



sewingtable.eu/manual/


- 7**  040003
 040002
 040001
 2x  030007 6x  030005



- 8** 4x  030006
 2x  020004

- 9** 030013
 8x  030013



- 11** 8x  030014 8x  030012

- 10**  030015
 8x

- 16** 020005
 1x  020005
 030001
 2x  030001




010001




010015

- 13** 030002
 4x  030002
 020008
 1x  020008

- 15** 6x  030002
 4x  030028
 2x 020018




- 12** 030008 030009
 2x  030008 2x  030009
 1x  020006

- 14** 020003
 1x  020003
 3x  030033



010009


040001





010009



010001




18



S10





24 020005
 1x 
 030001
 2x 



19 030008 030009
 2x  2x 
 1x  020006

26 
 1x 050003

 2x 050002 4x  030033


20 030002
 4x 
 020008
 1x 

27 030006
 2x 
 1x  020012



21 020011
 1x 
 4x  030002

23 6x  030002
 4x  030028
 
 2x 020018

22 020003
 1x 
 1x 
 3x  030033




25 030033
 8x 
 4x 050001

5x 010012



5x 010013





5x 010011

29


10x 030015



010028



010028





COMFORT 1Q+

37

3x



020019

12x

030033



010018

010020

36

16x

030033



4x 020019

35 020001

2x





2x

030004




010019

1x 050004




1x 010034





4



+



5

