


**SEWING MACHINE TABLE
COMFORT 3 (C3L, C3XL)**



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION




STORAGE




INDICATING MARK




SPECIAL OPERATION



WATCH























EQUALITY







EVEN SURFACE

010001	1 x	010002	1 x	010003	1 x
010004	1 x	010006	1 x	010007	1 x
010008	1 x	010009	1 x	010010	1 x
010011	2 x	010012	2 x	010013	2 x
010014	1 x	010023	1 x	010024	1 x
010025	1 x	010026	1 x	010027	1 x
010028	1 x	010029	1 x		

 020001 4x	 020002 2x	 020003 1x	 020004 1x 020005 1x	
 020006 2x	 020008 1x	 020010 1x L 660	 020011 1x	 020012 1x
 1x 020007		 1x 020009 L300		
 3x 020013 CR		 3x 020013 CL		
 3x 020015 DR		 3x 020015 DL		
 2x 020016		 2x 020017	 020021 4x	










030001  3 * 16 46x	030002  3,5 * 16 29x	030003  6,2 * 50 16x	030004  φ 5 * 16 6x	030005  4,2 * 16 10x	030006  2,9 * 13 4x	030007  φ 6 2x	030008  φ 4 4x	030009  M4 * 20 4x	030010  φ 6 4x
030011  φ 15 16x	030012  φ 18 17x	030013  L 35 17x	030014  φ 15 h 12 17x	030015  φ 8 * 30 18x	030016  φ 8 * 30 4x	030017  φ 15 h 10 4x	030020  3,5 * 20 4x	030022  M 4x	030023  φ 10 4x

030024  5 * 50 2x	030031  φ 10 s2,5 4x	030033  4,2 * 13 15x
--	---	---




4x  050001	2x  050002
1x  050003	1x  050006

1x  S3	1x  S4
---	---



* Included into table set.



11

4x 030001

2x 020015 DR

030016 **9**

4x

10

4x 030017

2x 010012

2x 010013

11

2x 020015 DL

4x 030001

2x 010011

8

4x 030015

14 2x 030024

2x 020017


12

1x 020015 DL

030001

2x

1x 010028



12

030001

2x

1x 020015 DR

13


030002






4x

2x 020016

1x 010029

15 1x 020009 10x 030001






010006


010014





010004

010007






sewingtable.eu/manual/shveystol.ru/ins.php





34



37




1x 050003




2x 050002

4x 
030033



030033



36

4x 050001

8x 
030033



1x 050006



