


SEWING MACHINE TABLE
COMFORT 9



SYMBOLS




ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION







INDICATING MARK



EVEN SURFACE

010001 1x	010002 2x	010004 1x	010006 1x
010007 1x	010011 2x	010012 2x	010013 2x
010015 1x	010020 2x	010026 1x	010028 1x
010030 1x	010033 1x	010034 1x	






S4
S5
S10
S12

2
8x 030011
8x 03003



1
030002
6x
020013 CR
3x






3
4x 030022
4x 030031
4x 030023
4x 020034

1
020013 CL
3x
030002
6x

4
6x 030011
6x 030003

6 020011
2x 
8x 
 030002

7 020003
2x 
6x 
 030033


5 030008 030009
4x  **4x** 
2x 
 020006

15 17 18

010007
 010015


8 **4x** 
 030006
2x 
 020004

010001



9 030015
4x 

10 030013
6x 

010015

11 **6x** 
 030014
6x 
 030012

010007

14 020005
2x 
4x 030001


12 **8x**  030028
12x  030002

4x 020018

13 020012 030006
2x  **4x** 

17 24x 030033


 6x 020019



16 16x 030033


 4x 020019


15 020001 030004
 2x  2x 



2x 010002

21

 1x 010034

20 4x 020020


030033 


~4MM

18 030033
 2x 
 1x 050001


19

 1x 050003

 1x 050002 2x 030033

22

4x 030001


2x 020015 DR

030016 **24**

4x

25


4x 030017



22

2x 020015 DL

4x 030001



26

1x 020015 DL


2x 030001

27

030002

4x

1x 050004



26

2x 030001

1x 020015 DR

