


SEWING MACHINE TABLE
COMFORT COMPACT



SYMBOLS




ATTENTION




ASSEMBLY & ADJUSTMENT



OPERATION








INDICATING MARK



EVEN SURFACE

010001 1x	010002 1x	010003 1x	010004 1x
010005 1x	010006 1x	010007 1x	010011 1x
010012 1x	010013 1x	010014 1x	010026 1x
010028 2x	030033 1x		





4

* Included into table set.

010002

010001



14 020005


1x

030001
2x

010005

8

030013
8x



010007

12

1x 020010

22x
030001

9

8x

030014

8x

030012

11 020003

1x

3x
030033









13 3x 030011





3x 030003

10 030008 030009

2x 2x

1x 020006





010011

