

***SEWING MACHINE TABLE***  
***COMFORT NEXT***



# ***SYMBOLS***




***ATTENTION***




***ASSEMBLY & ADJUSTMENT***



***OPERATION***



***INDICATING MARK***









***EVEN SURFACE***

010001	1 x	010003	1 x	010004	1 x
010006	1 x	010007	1 x	010013	1 x
010015	1 x	010023	1 x	010024	1 x
010025	1 x	010026	1 x	010027	1 x
010032	1 x	010038	1 x	010039	1 x
010040	1 x	010043	1 x		

<p>020001 2x      020002 2x</p>		<p>020004 2x</p>		<p>2x 020006</p>		<p>1x 020011</p>		<p>1x 020012</p>		<p>020018 4x</p>	
<p>2x 020013 CR</p>		<p>2x 020013 CL</p>		<p>2x 020016</p>		<p>020021 4x</p>					
<p>2x 020015 DL</p>		<p>2x 020015 DR</p>									

<p>030001 12x 3 * 16</p>	<p>030002 36x 3,5 * 16</p>	<p>030003 18x 6,2 * 50</p>	<p>030033 2x 4,2 * 13</p>	<p>030006 6x 2,9 * 13</p>	<p>030008 4x φ 4</p>	<p>030004 4x φ 5 * 16</p>
<p>030009 4x M4 * 20</p>	<p>030011 18x φ 15</p>	<p>030012 12x φ 18</p>	<p>12x 030013 L 35</p>	<p>030014 12x φ 15 h 12</p>	<p>030028 8x 3,9 * 16</p>	
<p>2x 030015 φ 8 * 30</p>	<p>2x 030016 φ 8 * 30</p>	<p>030017 2x φ 15 h 10</p>	<p>030022 4x M 10</p>	<p>030023 4x φ 10</p>	<p>030031 4x φ 10 s2,5</p>	


<p><b>1x</b>      <b>050002</b></p> 	<p><b>1x</b> <b>050004</b></p> 	<p><b>1x</b> <b>050005</b></p> 
<p><b>1x</b>      <b>050003</b></p> 		
<p><b>S4</b>      <b>1x</b></p> 		



010001

010004

**5**





010003

010006






\* Included into table set.










**14** 4x  030011  
4x  030003

**17**  
6x  030013

**13**  
030002  
4x  030002  
2x  020013 CR

**18**  
6x  030014  
6x  030012



**13**  
020013 CL  
2x  020013 CL  
4x  030002

**16** 6x  030011  
6x  030003

**15**  
4x  030022  
4x  030031  
4x  030023  
4x  020021

\* Included into table set.

