


SEWING MACHINE TABLE
COMFORT 1QLW (C 1QLW+)
COMFORT 1QXLW (C 1QXLW+)



SYMBOLS



ATTENTION




ASSEMBLY & ADJUSTMENT




OPERATION




STORAGE




INDICATING MARK




SPECIAL OPERATION



WATCH





































EQUALITY




EVEN SURFACE

010001	1x	010002	1x	010004	1x
010006	1x	010007	1x	010009	1x
010011	3x	010012	3x	010013	3x
010014	1x	010015	1x	010026	1x
010028	1x	010030	1x	010033	1x





 020003 2x	 020004 2x  020005 2x	 020006 2x	 020008 2x	 020011 1x
 020012 1x	 020018 4x		 4x 020034	
 4x 020013 CR		 4x 020013 CL		
 4x 020015 DR		 4x 020015 DL		

 3 * 16 20x	 3,5 * 16 44x	 6,2 * 50 19x	 4,2 * 16 10x	 2,9 * 13 6x	 φ6 2x	 φ4 4x	 M4 * 20 4x	 φ6 4x
 φ15 19x	 φ18 7x	 L 35 7x	 φ15 h 12 7x	 φ8 * 30 14x	 φ8 * 30 6x	 φ15 h 10 6x	 M 10 4x	 φ10 4x
 030031 φ10 s,5 4x	 030033 4,2 * 13 18x			 030028 3,9*16 8x				



COMFORT 1QXLW+




<p>010018 1x</p>	<p>020001</p> <p>2x</p> 	<p>7x 020019</p> 	<p>030004</p>  <p>$\phi 5 * 30$</p> <p>2x</p>	<p>030033</p>  <p>4,2 * 13</p> <p>28x</p>
-------------------------	---	--	---	---



S 4 *


S 5

S 10
S 12





sewingtable.eu/manual/



5 040003
040002
040001

2x 030007 6x 030005

6 4x 030006
2x 020004

8 030013
7x

010002

9 7x 030014 7x 030012

7 030015
8x

14 020005
1x 030001
2x

010015

010001


10 030002
4x 020008
1x



12 020003
1x 030033
x



15 6x 030002 4x 030028
2x 020018

11 030008 030009
2x 020006
1x



010009

040001




15

030005
4X




030010





010001



010009




16



S10



23 020005
 1x 
 030001
 2x 



17
 030008 030009
 2x  2x 
 1x  020006



25


 1x 050003




 2x 050002 4x  030033


18 030002
 4x 
 020008
 1x 

22 030006
 2x 
 1x  020012

19 020011
 1x 
 4x  030002

23
 6x  030002
 4x  030028
 
 2x 020018

20
 020003 
 1x 
 3x  030033



24 030033
 8x 
 4x 050001




29

6x 030001

3x 020015 DR

030016 **27**

6x

3x 010012

3x 010013

3x 010011

28

6x 030017

29


3x 020015 DL

6x 030001

26

030015

6x



32

1x 050005

030002


4x

31

030001

2x

1x 020015 DR



010028

31

030001

2x

1x 020015 DL



COMFORT 1QXLW+

35
3x



12x 
030033

020019

010018


010020

34 **16x** 
030033




4x 020019

33 **020001**








2x

2x 
030004



010019

1x 050004





4



+



5

