

***SEWING MACHINE TABLE***

***COMFOLOCK 1***



# ***SYMBOLS***



***ATTENTION***




***ASSEMBLY & ADJUSTMENT***




***OPERATION***




***STORAGE***




***INDICATING MARK***




***SPECIAL OPERATION***



***WATCH***

















***EQUALITY***













***EVEN SURFACE***


010001	1x	010002	1x	010003	1x	010004	1x
010005	1x	010006	1x	010007	1x	010009	1x
010026	1x						



 <b>020003</b> 1x	 <b>020004</b> 1x  <b>020005</b> 1x	 <b>1x 020006</b>  <b>1x 020010</b> L 660	 <b>2x</b> <b>020021</b>	 <b>2x</b> <b>020034</b>
--	--	---	--	---

 <b>030001</b> 3 * 16 <b>24x</b>	 <b>030003</b> 6,2 * 50 <b>13x</b>	 <b>030005</b> 4,2 * 16 <b>10x</b>	 <b>030006</b> 2,9 * 13 <b>2x</b>	 <b>030007</b> φ6 <b>2x</b>	 <b>030008</b> φ4 <b>2x</b>	 <b>030009</b> M4 * 20 <b>2x</b>
--	--	--	---	---	---	--

 <b>030010</b> φ6 <b>4x</b>	 <b>030011</b> φ15 <b>13x</b>	 <b>030012</b> φ18 <b>6x</b>	 <b>030013</b> L = 35 <b>6x</b>	 <b>030014</b> φ15 h12 <b>6x</b>	 <b>030015</b> φ8 * 30 <b>6x</b>
---	---	--	---	--	--




 <b>030022</b> M 10 <b>4x</b>	 <b>030023</b> φ 10 <b>4x</b>	 <b>030031</b> φ 10 s2,5 <b>4x</b>	 <b>030033</b> 4,2 * 13 <b>11x</b>
---	---	--	--







**4**

**\***  
*Included into table set.*




**12** 030008 030009  
 2x  2x   
 1x  020006

**6x** 030015 **6**  





**5** 2x   
 030006  
 1x  020004




**9** 020005  
 1x   
 030001  
 2x 

**7**  
 6x 030013  









**8**  
 6x  030014  
 6x  030012




**4** 040003  
 040002  
 040001  
 2x  030007 6x  030005


**10** 020003  
  
 1x   
 3x  030033


**11**  
 3x 030011   
 3x 030003 

**13**  
 22x  030001  
 1x 020010 


  
  
  
[sewingtable.eu/manual/shveystol.ru/ins.php](http://sewingtable.eu/manual/shveystol.ru/ins.php)





030033 



<b>16</b>	<b>8x</b>  <b>030033</b>
	<b>4x 050001</b>

